ASSIGNMENT 4

TEAM ID: PNT2022TMID06411

Name: Naganiranjana J

Project Name: IOT based smart

crop protection for agriculture

1.Write Code and connections in wokwi for ultrasonic sensor. whatever distance is less than 100 cms send "Alert" to ibm cloud aand display in device recent events.

```
Solution:
//Pins
const int TRIG_PIN = 7;
const int ECHO_PIN = 8;
//Anything over 400 cm (23200 us pulse) is "out of range"
const unsigned int MAX_DIST = 23200;
void setup() {
// The Trigger pin will tell the sensor to range find
Pin Mode(TRIG_PIN, OUTPUT);
digital Write(TRIG PIN, LOW);
//Set Echo pin as input to measure the duration of
//pulses coming back from the distance sensor
pinMode(ECHO_PIN, INPUT );
// We'll use the serial monitor to view the sensor output
Serial.begin(9600);
```

```
}
void loop() {
unsigned long t1;
```

```
unsigned long t2;
unsigned long pulse_width;
float cm;
float inches;
// Hold the trigger pin high for at least 10 us
digitalWrite(TRIG_PIN, HIGH);
delayMicroseconds(10);
digitalWrite(TRIG PIN, LOW);
// Wait for pulse on echo pin
while (digitalRead( ECHO_PIN )==0 );
// Measure how long the echo pin was held high (pulse width)
// Note: the micros() counter will overflow after-70 min
t1= micros ();
 while (digitalRead(ECHO_PIN) == 1);
 t2 = micros();
 pulse_width = t2-t1;
// Calculate distance in centimeters and inches. The constants
//are found in the datasheet, and calculated from the assumed speed
// of sound in air at sea level (- 340m/s)
cm=pulse_Width / 58;
inches = pulse_width/148.0;
```


```
// Print out results
if (pulse_width >MAX _ DIST ){
Serial.println("Out of range");
} else {
Serial.println("*********************************);
Serial.print("The Measured Distance in cm: ");
Serial.println(cm);
if( cm < 100 ){
   //while(true){
   Serial.println("Alert!!");
   //}
}
Serial.print("********************************);
}
//wait at least 1000ms before next measurement
Delay(1000);
}
```

Output:

1. If the distance is less than 100 cms, it alerts.

```
WOKWI SAVE - SHARE
                                                                                                                                                                                                    Docs (A)
 hc-sr04.ino diagram.json ● Library Manager ▼
                                                                                                              Simulation
                                                                                                                                                                                             ₫00:00.466 (%58%
          const int TRIG_PIN = 7;
const int ECHO_PIN = 8;
          // Anything over 400 cm (23200 us pulse) is "out of range"
const unsigned int MAX_DIST = 23200;
                                                                                                                                                                          // The Trigger pin will tell the sensor to range find
pinWode(TRIG_PIN, OUTPUT);
digitalWrite(TRIG_PIN, LOW);
                                                                                                                                      Bannata Parana
    11
12
13
14
15
16
17
18
19
20
21
22
23
                                                                                                                                      OO UNO
             //Set Echo pin as input to measure the duration of
//pulses coming back from the distance sensor
pinMode(ECHO_PIN, IMPUT);
            // We'll use the serial monitor to view the sensor output
Serial.begin(9600);
                                                                                                                                           void loop() {
            unsigned long t1;
unsigned long t2;
unsigned long pulse_width;
float cm;
float inches;
                                                                                                          ***********
                                                                                                          The Measured Distance in cm : 84.14
                                                                                                          Alert!!
                                                                                                                                                                                                   // Hold the trigger pin high for at least 10 us
```

2. If the distance is more than 100 cms, it won't alert



3. Simulation and code execution

