Problem statement: IoT Based Gas Leakage Monitoring and Alerting Systemfor industries..

Domain: Internet of Things

Assignment 2: Assume u get temperature and humidity values (generated with random function to a variable) and write a condition to continuously detect alarm in case of high temperature.

By,

KRISHNANANTH -720819106053

Python code:

import random

temp=random.randint(1,100)

humid=random.randint(1,100

) print(temp)

```
print(humid)
if(temp>30 & humid<50):

print("Alarm detected")
elif(temp>30 & humid>50):

print("Alarm detected")
elif(temp<30 & humid<50):

print("Alarm not detected")
elif(temp<30 & humid>50):

print("Alaram not detected")
```

OUTPUT:

i) 30 19

Alarm not detected.

ii) 57

97

Alarm detected.

```
■ 🌴 🕨 Flun 🥹 Debug 🔳 Stop 🚨 Shen
                                                                            FI Save
                                                                                                                                                                     Language Python 3 V (8 0
           import random
temp=random.re
           humid-random.
            print(temp)
print(humid)
  5 print(humid)
6 1f(temp>30 & humid<50):
7 print("Alarm detected")
8 elif(temp>30 & humid>50):
9 print("Alarm detected")
10 elif(temp<30 & humid>50):
11 print("Alarm not detected")
12 elif(temp<30 & humid>50):
13 print("Alaram not detected")
14
Alarm not detected
 ..Program finished with exit code 0 ress ENTER to exit console.
🖹 💠 ▶Run 🕲 Debug 🔳 Stop 🕒
                                                                               H Save {} Beautity #
                                                                                                                                                                       Language Python 3 × 6 0
 main.py
           import random
                                      undint(1,188)
      2 temp=random.
           humid-random.
     4 print(temp)
5 print(humid)
6 if(temp>30 % humid<50):
7 print("Alarm detected")
8 elif(temp>30 % humid>50):
9 print("Alarm detected")
   10 - elif(temp<30 & humid<50):

11 print("Alarm not detected")

12 - elif(temp<30 & humid>50):

13 print("Alaram not detected")
 v / s
Alarm detected
 ...Program finished with exit code 0
Press ENTER to exit console.
```