ASSIGNMENT -04 SANJAI P

QUESTION:


Write a code and connection in wokwi for ultrasonic sensor .whenever distance is less than 100 cms send alert.

CODE:

```
#define ECHO PIN 7
#define TRIG_PIN 4
void setup() {
 Serial.begin(115200);
 pinMode(LED_BUILTIN, OUTPUT);
 pinMode(TRIG_PIN, OUTPUT);
  pinMode(ECHO_PIN, INPUT);
  float readDistanceCM() {
  digitalWrite(TRIG_PIN, LOW);
  delay(2);
  digitalWrite(TRIG_PIN, HIGH);
  delay(10);
  digitalWrite(TRIG_PIN, LOW);
  int duration = pulseIn(ECHO_PIN, HIGH);
  return duration * 0.034 / 2;
void loop() {
 float distance = readDistanceCM();
  if (distance < 100){
  bool isNearby = distance < 100;</pre>
  digitalWrite(LED BUILTIN, isNearby);
  Serial.println("ALERT DETECTED ");
  Serial.print("Measured distance: ");
  Serial.println(readDistanceCM());
  delay(100);
  else {
  bool isNearby = distance > 100;
  digitalWrite(LED_BUILTIN, LOW);
  Serial.println("ALERT NOT DETECTED");
  Serial.print("Measured distance: ");
  Serial.println(readDistanceCM());
  delay(100);
```


SIMULATION:

ASSIGNMENT -04 SANJAI P



OUTPUT:

When it reaches less than 100 cm, alert is detected



ASSIGNMENT -04 SANJAI P

detected

