## **ASSIGNMENT 1**

NAME	KRISHNAMURTHY RE
TEAM ID	PNT2022TMID28556
PROJECT NAME	GAS LEAKAGE MONITORING
	AND ALERTING SYSTEM FOR
	INDUSTRIES

## **Code and Output**

```
import random
from time import sleep
while True:
  sleep(5)
  temperature = random.randrange(0, 200, 3)
  print("\nCurrent Temperature =",temperature,end="°C\n")
  humidity = random.randrange(0, 100, 6)
  print("Current Humidity =",humidity,end="%\n\n")
  if temperature >=38:
    print("Temperature >> High - Alarm ON")
  if humidity >= 75:
    print("Humidity >> High - Alarm ON")
  if temperature <=38:
    print("Temperature >> Low - Alarm OFF")
  if humidity <= 75:
    print("Humidity >> Low - Alarm OFF")
```

