```
int sensorState=0;
void setup()
 pinMode(2,INPUT);
 pinMode(13,OUTPUT);
 Serial.begin(9600);
void loop()
 //read the state of the sensor/digital input
 int a=digitalRead(2);
 //check the sensor pin is HIGH if it is set then
 //LED on
 if (sensorState=HIGH);
   digitalWrite(13,HIGH);
   Serial.println("Sensor activated");
   digitalWrite(13,LOW);
   delay(1000);
//Delay a little bit to improve simulation performance
```

