## **ASSIGNMENT-3 PYTHON CODE FOR RASPBERRY PI**

PROJECT: Hazardous Area Monitoring for Industrial Plant

Name: Ganesh P

## **LED BLINKING CODE:**

```
import RPI.GPIO as GPIO
from time import sleep
GPIO.setwarnings(False)
GPIO.setmode(GPIO.BOARD)
GPIO.setup(8, GPIO.OUT, initial-GPIO.LOW)
while True:
GPIO.output(8, GPIO.HIGH)
sleep(1)
GPIO.output(8, GPIO.LOW)
sleep(1)
```

## **TRAFFIC LIGHT CODE:**

sleep(1)

```
from gpiozero import LED from time import sleep
red = LED(22)
yellow = LED(27)
green = LED(17)
while True:
  red.on()
  sleep(15)
  red.off()
  sleep(1)
  yellow.on()
  sleep(10)
  yellow.off)
  sleep(1)
  green.on()
  sleep(10)
  green.off()
```