DEVELOP A PYTHON SCRIPT

Team ID	PNT2022TMID41669
Project Name	Hazardous Area Monitoring For Industrial Plant Powered by IoT

import time

import sys

import ibmiotf.application

import ibmiotf.device

import random

```
#Provide your IBM Watson Device Credentials
```

organization = "awb990"

deviceType = "NodeMCU"

deviceId = "12345"

authMethod = "token"

authToken = "12345678"

Initialize GPIO

def myCommandCallback(cmd):

print("Command received: %s" % cmd.data['command'])

status=cmd.data['command']

```
if status=="lighton":
    print ("led is on")
 elif status== "lightoff":
    print ("led is off")
  else:
    print ("please send proper command")
 #print(cmd)
try:
      deviceOptions = {"org": organization, "type": deviceType, "id": deviceId,
"auth-method": authMethod, "auth-token": authToken}
      deviceCli = ibmiotf.device.Client(deviceOptions)
      #.....
except Exception as e:
      print("Caught exception connecting device: %s" % str(e))
      sys.exit()
# Connect and send a datapoint "hello" with value "world" into the cloud as an
event of type "greeting" 10 times
deviceCli.connect()
while True:
```

```
#Get Sensor Data from DHT11
    temp=random.randint(90,100)
    Humid=random.randint(60,100)
    data = { 'temp' : temp, 'Humid': Humid }
    #print data
    def myOnPublishCallback():
      print ("Published Temperature = %s C" % temp, "Humidity = %s %%" %
Humid, "to IBM Watson")
    success = deviceCli.publishEvent("IoTSensor", "json", data, qos=0,
on_publish=myOnPublishCallback)
    if not success:
      print("Not connected to IoTF")
    time.sleep(1)
    deviceCli.commandCallback = myCommandCallback
# Disconnect the device and application from the cloud
deviceCli.disconnect()
```

OUTPUT:

Ln: 23 Col: 0