IBM ASSIGNMENT-3

TEAM ID: PNT2022TMID26661

NAME: THAMIZH SELVAN.L

ROLL NO: 212919106088

Build a python code. Assume u get temperature and humidity values (generated with random function to a variable) and write a condition to continuously detect alarm in case of high temperature.

program:

while True:

```
import RPi.GPIO as GPIO
import time
import signal
import sys
GPIO.setmode(GPIO.BCM)
GPIO.setup(9, GPIO.OUT)
GPIO.setup(10, GPIO.OUT)
GPIO.setup(11, GPIO.OUT)
def allLightsOff(signal, frame):
    GPIO.output(9, False)
    GPIO.output(10, False)
    GPIO.output(11, False)
    GPIO.cleanup()
    sys.exit(0)
signal.signal(signal.SIGINT, allLightsOff)
```

GPIO.output(9, True)

time.sleep(3)

GPIO.output(10, True)

time.sleep(1)

GPIO.output(9, False)

GPIO.output(10, False)

GPIO.output(11, True)

time.sleep(5)

GPIO.output(11, False)

GPIO.output(10, True)

time.sleep(2)

GPIO.output(10, False)