Karpagam College of Engineering

(Electronics and Communication Engineering)

Name: Subaash G

Roll No: 717819L245

Assignment 2:

Temperature and Humidity sensing alarm automation using python

Code:

```
import random
while(1):
    temperature=random.randint(9,30)  #random temperature between 9 and 30
    humidity=random.randint(15,55)     #random humidity between 15 and 55
    if (temperature>10 and humidity>50):
        print("high temperature and humidity -->",temperature,humidity,"%","Alarm ON")
        break
    elif(temperature<10 and humidity<50):
        print("Normal temperature and humidity  -->",temperature,humidity,"%","Alarm OFF")
        break
```

Language Python 3 ˅

main.py

```python
import random
while(1):
    temperature=random.randint(9,30)   #random temperature between 9 and 30
    humidity=random.randint(15,55)         #random humidity between 15 and 55
    if (temperature>10 and humidity>50):
        print("high temperature and humidity -->",temperature,humidity,"%","Alarm  ON")
        break
    elif(temperature<10 and humidity<50):
        print("Normal temperature and humidity  -->",temperature,humidity,"%","Alarm OFF")
        break
```

input

```
high temperature and humidity --> 17 51 % Alarm  ON

...Program finished with exit code 0
Press ENTER to exit console.
```