GAS LEAKAGE MONITORING&ALERTING SYSTEM FOR INDUSTRIES

PROJECT DEVELOPMENT PHASE

SPRINT 1:

| TITLE | GAS LEAKAGE |
|-------------|--------------------------------|
| | MONITORING&ALTERING SYSTEM FOR |
| | INDUSTRIES |
| DOMAIN NAME | INTERNET OF THINGS |
| | |
| TEAM ID | PNT2022TMID16039ss |
| | |

PROGRAM:

```
#include <LiquidCrystal.h>
LiquidCrystal lcd(5,6,8,9,10,11);
int redled = 2:
int greenled = 3;
int buzzer = 4;
int sensor =A0;
int sensorThresh = 400;
void setup()
pinMode(redled, OUTPUT);
pinMode(greenled,OUTPUT);
pinMode(buzzer,OUTPUT);
pinMode(sensor,INPUT);
Serial.begin(9600);
lcd.begin(16,2);
}
void loop() {
                int analogValue =
analogRead(sensor);
Serial.print(analogValue);
if(analogValue>sensorThresh)
  digitalWrite(redled,HIGH);
digitalWrite(greenled,LOW);
tone(buzzer, 1000, 10000
     lcd.clear();
);
lcd.setCursor(0,1);
lcd.print("ALERT");
delay(1000);
lcd.clear();
  lcd.setCursor(0,1);
lcd.print("EVACUATE");
```

```
delay(1000);
else
  digitalWrite(greenled,HIGH);
digitalWrite(redled,LOW);
noTone(buzzer);
  lcd.clear();
lcd.setCursor(0,0);
lcd.print("SAFE");
delay(1000);
lcd.clear();
lcd.setCursor(0,1);
lcd.print("ALL
CLEAR");
  delay(1000);
 }
}
```