GAS LEAKAGE MONITORING&ALERTING SYSTEM FORINDUSTRIES

PROJECT DEVELOPMENT PHASE

```
TEAM ID: PNT2022TMID16039
SPRINT 4:
PROGRAM:
 #include <LiquidCrystal.h> LiquidCrystal
 lcd(5,6,8,9,10,11);
 int redled = 2; int
 greenled = 3; int
 buzzer = 4; int sensor
 = A0;
 int sensorThresh = 400;
 void setup()
 pinMode(redled, OUTPUT);
 pinMode(greenled,OUTPUT);
 pinMode(buzzer,OUTPUT);
 pinMode(sensor,INPUT); Serial.begin(9600);
lcd.begin(16,2);
 void loop() {
  int analogValue = analogRead(sensor);
 Serial.print(analogValue);
if(analogValue>sensorThresh)
  {
    digitalWrite(redled,HIGH);
digitalWrite(greenled,LOW);
    tone(buzzer, 1000, 10000); lcd.clear();
                  lcd.setCursor(0,1);
 lcd.print("ALERT"); delay(1000);
    lcd.clear();
   lcd.setCursor(0,1);
lcd.print("EVACUATE");
   delay(1000);
```