GAS LEAKAGE MONITORING&ALERTING SYSTEM FORINDUSTRIES

PROJECT DEVELOPMENT PHASE

SPRINT 4:

TITLE	GAS LEAKAGE			
	MONITORING&ALTERING SYSTEM FOR			
	INDUSTRIES			
DOMAIN NAME	INTERNET OF THINGS			
TEAM ID	PNT2022TMID16039			

PROGRAM:

```
#include <LiquidCrystal.h> LiquidCrystal
1cd(5,6,8,9,10,11);
int redled = 2; int
greenled = 3; int
buzzer = 4; int sensor
= A0:
int sensorThresh = 400;
void setup()
pinMode(redled, OUTPUT);
pinMode(greenled,OUTPUT);
pinMode(buzzer,OUTPUT);
pinMode(sensor,INPUT); Serial.begin(9600);
lcd.begin(16,2);
void loop() {
 int analogValue = analogRead(sensor);
Serial.print(analogValue);
if(analogValue>sensorThresh)
 {
   digitalWrite(redled,HIGH);
digitalWrite(greenled,LOW);
   tone(buzzer,1000,10000); lcd.clear();
                 lcd.setCursor(0,1);
lcd.print("ALERT"); delay(1000);
   lcd.clear();
   lcd.setCursor(0,1);
lcd.print("EVACUATE");
   delay(1000);
else
 {
   digitalWrite(greenled,HIGH);
digitalWrite(redled,LOW);
   noTone(buzzer); lcd.clear();
lcd.setCursor(0,0);
lcd.print("SAFE"); delay(1000);
```

```
lcd.clear();
lcd.setCursor(0,1); lcd.print("ALL
CLEAR");
   delay(1000);
}
```