## GAS LEAKAGE MONITORING&ALERTING SYSTEM FOR INDUSTRIES

## PROJECT DEVELOPMENT PHASE

## **SPRINT 2:**

TITLE	GAS LEAKAGE		
	MONITORING&ALTERING SYSTEM FOR		
	INDUSTRIES		
DOMAIN NAME	INTERNET OF THINGS		
TEAM ID	PNT2022TMID16039		

## **PROGRAM:**

```
#include <LiquidCrystal.h> LiquidCrystal
lcd(5,6,8,9,10,11);
int redled = 2; int
greenled = 3; int
buzzer = 4; int
sensor =A0;
int sensorThresh = 400;
void setup()
pinMode(redled, OUTPUT);
pinMode(greenled,OUTPUT);
pinMode(buzzer,OUTPUT);
pinMode(sensor,INPUT);
Serial.begin(9600); lcd.begin(16,2);
}
void loop() {
                  int analogValue =
analogRead(sensor);
Serial.print(analogValue);
if(analogValue>sensorThresh)
   digitalWrite(redled,HIGH);
digitalWrite(greenled,LOW);
tone(buzzer, 1000, 10000)
    lcd.clear();
lcd.setCursor(0,1);
lcd.print("ALERT");
delay(1000);
lcd.clear();
  lcd.setCursor(0,1);
lcd.print("EVACUATE");
   delay(1000);
 else
 {
   digitalWrite(greenled,HIGH);
digitalWrite(redled,LOW);
   noTone(buzzer);
lcd.clear();
lcd.setCursor(0,0);
```

```
lcd.print("SAFE");
delay(1000); lcd.clear();
lcd.setCursor(0,1);
lcd.print("ALL
CLEAR");
    delay(1000);
}
```