## **Customer Journey Map**

<b>1</b> Phases	Entire power plant is used by user	Check temperature of current location	User enters hazardous area	Alert the authorities and take necessary actions
2 Steps	User obtains wearable device from the power plant supervisors  user wears smart wearable all the time theywork	User continuously monitor the smart wearables The temperature isdisplayed on the wearable	Checks whether the temperature is within its limit  if the temperature gets above the limit then gets alerted.	User get informed via SMS and also through an API  Authorities also gets notified of this issue, and take necessary actions needed.
• Feelings	Feeling of ease knowing they will be informed in case of any risks  ease due to constant awareness of	they would be calm as their wearable indicate the safeness of the	lucky that they are informed of their current danger	Thankful for the information to take the necessary precautions
7'	fear of the about theirlife hazard	Worry for sudden change of the situation	they are in fear of their situation-	Stress to make the necessary announcements and changes as soon as possible
Pain points	They may not get the informationon time	Users must constantly check the wearable device for signs of changes	Users informed of the present danger suddenly with no warning	The admin having to make sudden and immediate decisions to ensure a large number of worker'ssafety
Opportunities	Make a small and compatible wearable device which the user can wear at all times	Constantly updating the wearable devices data informing the user of the current situation	User can also be informed incase changes are happeningrapidly	Admins make necessary announcements asall data is seen by them from beaconsthrough the cloud