ASSIGNMENT - 4

Write a code and connections in wokwi for ultrasonic sensor. Whenever distance is less than 100 cms "send" alert to IBM Cloud and display in device recent events

Coding:

```
//set pins
#define echoPin 7
#define trigPin 6
//initialise variables
long duration;
int distance;
void setup(){
//set input and output
 pinMode(trigPin, OUTPUT);
 pinMode(echoPin, INPUT);
 Serial.begin(9600);
//create serial connections
}
void loop() {
//set trigger pin to low
 digitalWrite(trigPin, LOW);
//apply delay
 delayMicroseconds(2);
//set trigger pin high
 digitalWrite(trigPin, HIGH);
 delayMicroseconds(10);
 digitalWrite(trigPin, LOW);
//set trigger pin low
 duration = pulseIn(echoPin, HIGH);//find the pulse in the echo pin
 distance = duration * 0.034 / 2;//formula for finding the distance
 Serial.print("Distance: ");
 Serial.print(distance);//print distance
 Serial.println(" cm");
 if(distance<100){
  Serial.println("Alert");//if distance greater than 100cm alert
 }
}
```

Output

