## **Assignment 4**

Team Id	PNT2022TMID14029
Project Name	Gas Leakage Monitoring and Alerting
	System for Industries
Roll No	711319cs119

Write a code and connections in wokwi for ultrasonic sensor. Whenever distance is less than 100 cms "send" alert to IBM Cloud and display in device recent events

## **Program Coding**

```
#include "Ultrasonic.h"
Ultrasonic ultrasonic(12, 13);
int distance;
void setup() {
Serial.begin(9600);
}
void loop() {
// Pass INC as a parameter to get the distance in inches
distance = ultrasonic.read(CM);
Serial.print("Distance in CM: ");
Serial.println(distance);
if (distance < 100)
Serial.print("alert");
Serial.println();
delay(1000);
}
```

## **Output**

