GAS LEAKAGE MONITORING AND ALERTING SYSTEM FOR INDUSTRIES ASSIGNMENT-2

SOURCE CODE:

```
import time
import random
i=0
while(i<=2000):
  i=i+1
  time.sleep(2)
  temp=random.randint(0,30)
  humid=random.randint(1,100)
  if temp<=15:
    print (temp, "the temperature is low, ALARM IS OFF")
  elif temp<=25:
    print (temp, "the temperature is normal, ALARM IS OFF")
  else:
    print (temp, "the temperature is high, ALARM IS ON")
  if humid<=15:
    print (humid, "the humidity is low, ALARM IS OFF")
  elif humid<=80:
    print (humid, "the humidity is normal, ALARM IS OFF")
  else:
    print (humid, "the humidity is high, ALARM IS ON")
```