## **IBM Assignment 3**

Project Title: Gas Leakage Monitoring and Alerting System for Industries

Team Member: SURIYAPRAKASH S SUJITH M RAJESH G RAGUL R CODE: # code for light blinking import RPi.GPIO as GPIO import time LED = 40 GPIO.setwarnings(False) GPIO.setmode(GPIO.BOARD) GPIO.setup(LED, GPIO.OUT) while True: GPIO.output(LED,GPIO.HIGH) time.sleep(1) GPIO.output(LED,GPIO.LOW) time.sleep(1) //Code for Traffic Light System// from gpiozero import Button, TrafficLights, Buzzer from time import sleep buzzer = Buzzer(15) button = Button(21) lights = TrafficLights(25, 8, 7) while True: button.wait\_for\_press() buzzer.on() light.green.on() sleep(1) lights.amber.on() sleep(1) lights.red.on() sleep(1) lights.off() buzzer.off()