Department of Electronics and Communication Engineering

IOT Assignment

Topic: Assignment on temperature and humidity sensing and alarm automation using python

Name: R.Kavin Kumar

Code:

```
import random
Temperature=random.randint(10,60)
Humidity=random.randint(10,90)
if(Temperature>=31 and Temperature<=40):
    print("Normal Temperature")
elif(Temperature<31):
    print("Low Temperature")
else:
    print("High Temperature")
if(Humidity<30):
    print("Low Humidity")
elif(Humidity>50):
    print("High Humidity")
else:
    print("Normal Humidity")
```

OUTPUT:

