


Assignment-4


Question-1:

Write code and connections in wokwi for ultrasonic sensors. Whenever distance is less than 100 cms send "alert" to ibm cloud and display in device recent events.










DATA SENT TO IBM CLOUD ON NO OBJECT DETECTED



WHEN OBJECT DETECTED BY ULTRASONIC DETECTOR SENSOR

