```
#include<Servo.h>
const int pingPin = 7;
int servoPin = 9;
Servo servo1;
void setup() {
 Serial.begin(9600);
 servo1.attach(servoPin);
 pinMode(2,INPUT);
 pinMode(4,OUTPUT);
 pinMode(11,OUTPUT);
 pinMode(12,OUTPUT);
 pinMode(13,OUTPUT);
 pinMode(A0,INPUT);
 digitalWrite(2,LOW);
 digitalWrite(11,HIGH);
void loop() {
 long duration, inches, cm;
 pinMode(pingPin, OUTPUT);
 digitalWrite(pingPin, LOW);
 delayMicroseconds(2);
 digitalWrite(pingPin, HIGH);
 delayMicroseconds(5);
 digitalWrite(pingPin, LOW);
 pinMode(pingPin, INPUT);
 duration = pulseIn(pingPin, HIGH);
 inches = microsecondsToInches(duration);
 cm = microsecondsToCentimeters(duration);
 servo1.write(0);
 if(cm < 35)
  servo1.write(100);
  delay(2000);
 else
  servo1.write(0);
```

```
int pir = digitalRead(2);
 if(pir == HIGH)
  digitalWrite(4,HIGH);
  delay(50);
 else if(pir == LOW)
  digitalWrite(4,LOW);
 float value=analogRead(A0);
 float temperature=value*0.48;
 Serial.println(temperature);
 if(temperature > 25)
  digitalWrite(12,HIGH);
  digitalWrite(13,LOW);
 else
  digitalWrite(12,LOW);
  digitalWrite(13,LOW);
long microsecondsToInches(long microseconds) {
 return microseconds / 74 / 2;
long microsecondsToCentimeters(long microseconds) {
return microseconds / 29 / 2;
}
```