

111519106156


SURENDAR S

ASSIGNMENT 1: PIEZO ALARM AND PIR SENSOR





OUTPUT:



Code: void setup()

```
{
Serial.begin(9600);
pinMode(9, OUTPUT);
pinMode(4, INPUT);
void loop()
{
int
tempdata=analogRea
d(0); int
pirdata=digitalRead(4
);
Serial.println(tempda
ta); if(tempdata>60){
tone(9,3500,500);
delay(1000);
}
if(pirdata==1){
    tone(9,5000,500);
delay(1000);
}
```

```
digitalWrite(9,LOW);
}
```