GAS LEAKAGE MONITORING&ALERTING SYSTEM FOR INDUSTRIES

IBM NALAIYATHIRAN

PROJECT DEVELOPMENT PHASE

SPRINT 4:

GAS LEAKAGE
MONITORING&ALTERING SYSTEM FOR
INDUSTRIES
INTERNET OF THINGS
PNT2022TMID30401

PROGRAM:

```
#include <LiquidCrystal.h>
LiquidCrystal lcd(5,6,8,9,10,11);
int redled = 2; int
greenled = 3; int
buzzer = 4; int
sensor = A0:
int sensorThresh = 400;
void setup()
pinMode(redled, OUTPUT);
pinMode(greenled,OUTPUT);
pinMode(buzzer,OUTPUT);
pinMode(sensor,INPUT);
Serial.begin(9600); lcd.begin(16,2);
void loop() {
 int analogValue = analogRead(sensor);
Serial.print(analogValue);
if(analogValue>sensorThresh)
  digitalWrite(redled,HIGH);
digitalWrite(greenled,LOW);
  tone(buzzer, 1000, 10000);
lcd.clear();
           lcd.setCursor(0,1);
lcd.print("ALERT");
delay(1000);
  lcd.clear();
```

```
lcd.setCursor(0,1);
lcd.print("EVACUATE");
  delay(1000);
 }
else
  digitalWrite(greenled,HIGH);
digitalWrite(redled,LOW);
  noTone(buzzer);
lcd.clear();
lcd.setCursor(0,0);
lcd.print("SAFE");
delay(1000);
             lcd.clear();
lcd.setCursor(0,1);
lcd.print("ALL CLEAR");
  delay(1000);
 }
```