SMART FARMER – IoT ENABLED SMART FARMER APPLICATION ASSIGNMENT – 4


Team ID	PNT2022TMID03604
Name	RISHANTH RAJ R
Roll No.	212219060218

1. Write Code and connections in wokwi for ultrasonic sensor. Whenever distance is less than 100 centimetres send an 'alert' to the ibm cloud and display in device recent events.

Program:


```
#define ECHO PIN 2
#define TRIG PIN 3
void setup() {
 Serial.begin(115200);
pinMode(LED BUILTIN, OUTPUT);
pinMode(TRIG PIN, OUTPUT);
pinMode(ECHO PIN, INPUT);
float readDistanceCM() {
digitalWrite(TRIG PIN, LOW);
delayMicroseconds(2);
digitalWrite(TRIG_PIN, HIGH);
delayMicroseconds(10);
 digitalWrite(TRIG PIN, LOW);
 int duration = pulseIn(ECHO PIN, HIGH);
 return duration * 0.034 / 2;
}
void loop() {
 float distance = readDistanceCM();
 if(distance<100)
 Serial.println("Alert!!!!!!");
 Serial.print("Measured distance: ");
 Serial.println(readDistanceCM());
delay(100);
```

Wokwi Editor window:



Results:

1. The measured distance is less than 100 centimetres, it gives alert message



2. The measured distance is more than 100 centimetres, it will not give alert message

