CODE

```
int t=2;
int e=3;
void setup()
 pinMode(13,OUTPUT);
 pinMode(12,OUTPUT);
 pinMode(13,OUTPUT);
 pinMode(t,OUTPUT);
 pinMode(e,INPUT);
 Serial.begin(9600);
void loop()
digitalWrite(13,HIGH);
 Serial.println("LED ON");
 {tone(12,131);
 delay(1000);
  double a = analogRead(A0);
  double c = (((a/1024)*5)-0.5)*100;
  Serial.print("celsius value:");
  Serial.println(c);
  delay(1000);
  digitalWrite(t,LOW);
  digitalWrite(t,HIGH);
  delay(10);
  digitalWrite(t,LOW);
  float dur = pulseln(e,HIGH);
  float dis = (dur^*0.0343)/2;
  Serial.print("Distance is");
  Serial.println(dis);
```

MODEL

