ASSIGNMENT-3

MAHESWARI J 710719104057

Dr. N.G.P. INSTITUTE OF TECHNOLOGY

BLINKING LED CODE:

```
import RPi.GPIO as GPIO
from time import sleep

GPIO.setwarnings(False)
GPIO.setmode(GPIO.BOARD)
GPIO.setup(8,GPIO.OUT,initial=GPIO.LOW)

while True:
GPIO.output(8,GPIO.HIGH)
sleep(1)
GPIO.output(8,GPIO.LOW)
sleep(1)
```

TRAFIC LIGHTS CODE:

```
from gpiozero import Button, TrafficLights, Buzzerfrom time import sleep
buzzer = Buzzer (15)
button = Button(21)
lights = TrafficLights (25, 8, 7)
while True:
button.wait_for_press()
```

buzzer.on()
lights.green.on()
sleep(1)
lights.amber.on()
sleep(1)
lights.red.on()
sleep(1) lights.off()
buzzer.off()