```
# Python code for LED blinking using RASPBERRY Pi
import sys
import time
import RPi.GPIO as GPIO
                             #importing GPIO library
LED_PIN = 17
GPIO.setmode(GPIO.BCM)
GPIO.setup(LED_PIN, GPIO.OUT)
while True:
  GPIO.output(LED_PIN, GPIO.HIGH) #turning ON LED
  time.sleep(0.5)
                         #waiting for 0.5 seconds
  GPIO.output(LED_PIN, GPIO.LOW) #turning OFF LED
  time.sleep(0.5)
                         #waiting for 0.5 seconds
GPIO.cleanup()
```