IOT ASSIGNMENT 2

TOPIC: *Assignment on temperature and humidity sensing and alarm automation using python*

NAME:

R.AYYAR SELVAM-19EC012

M.BALAKRISHNAPRAKASH-19EC013

K.HARIDINESHKUMAR-19EC030

K.HARIRAAM-19EC031

```
CODE:
        import random

        while(True):
        a=random.randint(10,100)
        b=random.randint(10,100)
      if(a>35 and b>65):
            print("HIGH TEMPERATURE AND HUMIDITY OF:",a,b,"%","ALARM IS ON")
            continue
    elif(a<35 and b<65):
        print("NORMAL TEMPERATURE AND HUMIDITY OF:",a,b,"%","ALARM IS OFF")
        break
```

OUTPUT :-


```python
import random
while(True):
    a=random.randint(10,100)
    b=random.randint(10,100)
    if(a>35 and b>65):
        print("HIGH TEMPERATURE AND HUMIDITY OF:",a,b,"%","ALARM IS ON")
        continue
    elif(a<35 and b<65):
        print("NORMAL TEMPERATURE AND HUMIDITY OF:",a,b,"%","ALARM IS OFF")
        break
```

```
HIGH TEMPERATURE AND HUMIDITY OF: 68 96 % ALARM IS ON
HIGH TEMPERATURE AND HUMIDITY OF: 81 83 % ALARM IS ON
NORMAL TEMPERATURE AND HUMIDITY OF: 13 32 % ALARM IS OFF


...Program finished with exit code 0
Press ENTER to exit console.
```