## **PYTHON SCRIPT**

Date	16 NOVEMBER 2022
Team ID	PNT2022TMID32982
Project Name	INDUSTRY-SPECIFIC INTELLIGENT FIRE MANAGEMENT SYSTEM
Maximum Marks	4 Marks

## **PYTHON CODE**

```
import time
import sys
import ibmiotf.application
import ibmiotf.device
import random
```

```
#Provide your IBM Watson Device Credentials
organization = "56axre"
deviceType = "raspberrypi"
deviceId = "123"
authMethod = "token"
authToken = "12345678"
# Initialize GPIO
```

```
def myCommandCallback(cmd):
    print("Command received: %s" % cmd.data['command'])
    status=cmd.data['command']
    if status=="alarmon":
        print ("Alarm is on")
```

```
else:
    print ("Alarm is off")
  #print(cmd)
try:
deviceOptions = {"org": organization, "type": deviceType, "id": deviceId, "auth-method":
authMethod, "auth-token": authToken}
deviceCli = ibmiotf.device.Client(deviceOptions)
#.....
except Exception as e:
print("Caught exception connecting device: %s" % str(e))
sys.exit()
# Connect and send a datapoint "hello" with value "world" into the cloud as an event of
type "greeting" 10 times
deviceCli.connect()
while True:
    #Get Sensor Data from DHT11
    temp=random.randint(0,100)
    Humid=random.randint(0,100)
    data = { 'temp' : temp, 'Humid': Humid }
    #print data
    def myOnPublishCallback():
```

```
print ("Published Temperature = %s C" % temp, "Humidity = %s %%" % Humid, "to
IBM Watson")

success = deviceCli.publishEvent("IoTSensor", "json", data, qos=0,
on_publish=myOnPublishCallback)

if not success:
    print("Not connected to IoTF")

time.sleep(10)

deviceCli.commandCallback = myCommandCallback
```

# Disconnect the device and application from the cloud deviceCli.disconnect()

## **OUTPUT**

