PERSONAL ASSISTANCE FOR SENIORS WHO ARE SELF-RELIANT


Assignment -4

Question:

Write a code and connection in wokwi for ultrasonic sensor .whenever distance is less than 100 cms send alert.

Solution:

SIMULATION




CODE


```
#define ECHO_PIN 2
#define TRIG_PIN 9
void setup()
Serial.begin(115200);
 pinMode(LED_BUILTIN, OUTPUT);
 pinMode(TRIG_PIN, OUTPUT);
 pinMode(ECHO_PIN, INPUT);
 float readDistanceCM()
 digitalWrite(TRIG PIN, LOW);
 delay(2);
 digitalWrite(TRIG_PIN, HIGH);
 delay(10);
 digitalWrite(TRIG_PIN, LOW);
 int duration = pulseIn(ECHO_PIN, HIGH);
 return duration * 0.034 / 2;
void loop()
 float distance = readDistanceCM();
 if (distance < 100)
 {
 bool is Nearby = distance < 100;
 digitalWrite(LED BUILTIN, isNearby);
 Serial.println("ALERT DETECTED ");
 Serial.print("Measured distance: ");
 Serial.println(readDistanceCM());
 delay(100);
 }
 else
 bool isNearby = distance > 100;
 digitalWrite(LED BUILTIN, LOW);
 Serial.println("ALERT NOT DETECTED");
 Serial.print("Measured distance: ");
 Serial.println(readDistanceCM());
 delay(100);
 }
```

<u>OUTPUT</u>

When it reaches less than 100 cm, alert is detected



When the distance is greater than 100 cm , alert is not detected



PROGRAM AND OUTPUT

```
#define ECHO_PIN 7
                                                                                                                                                00:21.184 (4)86%
 2 #define TRIG_PIN 4
 3 void setup() {
    Serial.begin(115200);
      pinMode(TRIG_PIN, OUTPUT);
      pinMode(ECHO_PIN, INPUT);
      float readDistanceCM() {
      digitalWrite(TRIG_PIN, LOW);
      delay(2);
      digitalWrite(TRIG_PIN, HIGH);
      delay(10);
      digitalWrite(TRIG_PIN, LOW);
      int duration = pulseIn(ECHO_PIN, HIGH);
     return duration * 0.034 / 2;
18 void loop() {
      float distance = readDistanceCM();
                                                                               Measured distance: 86.50
      if (distance < 100){</pre>
                                                                               ALERT DETECTED
      bool isNearby = distance < 100;</pre>
                                                                               Measured distance: 86.50
      digitalWrite(LED BUILTIN, isNearby);
       Serial.println("ALERT DETECTED ");
                                                                               ALERT DETECTED
       Serial.print("Measured distance: ");
                                                                               Measured distance: 86.50
       Serial.println(readDistanceCM());
                                                                               ALERT DETECTED
      delay(100);
                                                                               Measured distance: 86.50
```

REFERENCE LINK

https://wokwi.com/projects/346827261526147666