



```
#include <Servo.h>
int output 1 Value = 0;
int sen1Value = 0;
int sen 2 Value = 0;
int const gas_sensor = A1;
int const LDR = A0;
int limit = 400;
long readUltrasonicDistance(int trigerrPin, int echoPin)
 pinMode(trigerrPin, OUTPUT);
 digitalWrite(trigerrPin, LOW);
 delayMicroseconds(2);
 digitalWrite(trigerrPin, HIGH);
 delayMicroseconds(10);
 digitalWrite(trigerrPin, LOW);
 pinMode(echoPin, INPUT);
 pinMode(echoPin, HIGH);
Servo servo 7;
void setup()
 Serial.begin(9600);
 pinMode(A0, INPUT);
 pinMode(A1, INPUT);
 pinMode(13, OUTPUT);
 servo 7.attach(7, 500, 2500);
 pinMode(8, OUTPUT);
 pinMode(9, INPUT);
 pinMode(10, OUTPUT);
 pinMode(4, OUTPUT);
 pinMode(3, OUTPUT);
void loop()
 int vall = analogRead(LDR);
 if (vall > 500)
  digitalWrite(13, LOW);
  Serial.print("Bulb on =");
  Serial.print(vall);
else
 digitalWrite(13, HIGH);
  Serial.print("Bulb off =");
  Serial.
```