Hazardous Area Monitering For Industrial Plant Powered by IOT

Assignment - II

Topic: PYTHON CODE TO GET TEMPERATURE AND

HUMIDITY VALUE

Name: NAGA VISHWA G

RegisterNumber: 920819106039

E-Mail Id: naganaga9821@gmail.com

Code: Import

random

From playsound import playsound

```
While True:
    # generating temperature values
    Temperature = random.uniform(-25, 45)

# generating relative humidity values
    Humidity = random.uniform(0, 100)

# calculating the dew point temperature
```

 $Dew_point = temperature - ((100 - humidity)/5)$

If dew_point < 16:

Print("The weather is comfortable!")

Elif dew_point < 18 and dew_point >= 16:

Print("The weather is slightly uncomfortable")

Else:

Print("The weather is extremely uncomfortable")

Playsound('/Users/macbook/Desktop/IBM Project/Assignment 2/alarm.wav')