
DEVELOP A PYTHON SCRIPT

TEAM ID	PNT2022TMID34892
PROJECT NAME	Smart Waste Management System For
	Metropolitan Cities



```
def myCommandCallback(cmd):
  global a
  print("command recieved:%s" %cmd.data['command'])
  control=cmd.data['command']
  print(control)
try:
    deviceOptions={"org": organization, "type": devicType, "id": deviceId, "auth-
method":authMethod,"auth-token":authToken}
    deviceCli = ibmiotf.device.Client(deviceOptions)
except Exception as e:
    print("caught exception connecting device %s" %str(e))
    sys.exit()
#connect and send a datapoint "temp" with value integer value into the cloud as a type of
event for every 10 seconds
deviceCli.connect()
while True:
  distance= random.randint(10,70)
  loadcell= random.randint(5,15)
  data= {'dist':distance,'load':loadcell}
```

```
if loadcell < 13 and loadcell > 15:
  load = "90 %"
elif loadcell < 8 and loadcell > 12:
   load = "60 %"
elif loadcell < 4 and loadcell > 7:
   load = "40 %"
else:
   load = "0 %"
if distance < 15:
   dist = 'Risk warning:' 'Dumpster poundage getting high, Time to collect :) 90 %'
elif distance < 40 and distance >16:
   dist = 'Risk warning:' 'dumpster is above 60%'
elif distance < 60 and distance > 41:
   dist = 'Risk warning:' '40 %'
else:
   dist = 'Risk warning:' '17 %'
```

```
if load == "90 %" or distance == "90 %":
     warn = 'alert:' ' Dumpster poundage getting high, Time to collect:)'
  elif load == "60 %" or distance == "60 %":
     warn = 'alert :' 'dumpster is above 60%'
  else:
     warn = 'alert :' 'No need to collect right now '
  def myOnPublishCallback(lat=10.678991,long=78.177731):
    print("Gandigramam, Karur")
    print("published distance = %s " %distance,"loadcell:%s " %loadcell,"lon = %s " %long,"lat =
%s" %lat)
    print(load)
    print(dist)
    print(warn)
  time.sleep(10)
  success=deviceCli.publishEvent ("IoTSensor","json",warn,qos=0,on_publish=
myOnPublishCallback)
```

success=deviceCli.publishEvent ("IoTSensor","json",data,qos=0,on_publish=myOnPublishCallback)
if not success:
print("not connected to ibmiot")
time.sleep(30)
deviceCli.commandCallback=myCommandCallback
#disconnect the device
deviceCli.disconnect()