```
int moisture data = 0;
void setup()
pinMode(A0, INPUT);
Serial.begin(9600);
pinMode(13, OUTPUT);
pinMode(6, OUTPUT);
}
void loop()
moisture_data = analogRead(A0);
Serial.println(moisture_data);
if (moisture_data< 21) {
digitalWrite(13, HIGH);
digitalWrite(6, HIGH);
}
else {
digitalWrite(13, LOW);
digitalWrite(6, LOW);
delay(10);
}
```