PROGRAM FOR TEMPERATURE AND HUMIDITY TO INDICATE ALARM CONTINUOUS IN HIGH TEMPERATURE USING GENERATED RANDOM VARIABLES:

```
Import random
While (True):
Temp=random.randint(30,100)
Hum=random.randint(30,100)
If (Temp>=50 and Hum<=80):
    Print ("high temperature values of temperature and humidity is:",Temp,Hum);
    Print("alarm ON");
Elif(Temp<50 and Hum>80):
    Print ("low temperature values of temperature and humidity is:",Temp,Hum);
    Print ("alarm OFF");
```

```
high temperatures values of temperature and humidity is : 66 66
alarm ON
high temperatures values of temperature and humidity is : 94 66
alarm ON
high temperatures values of temperature and humidity is : 74 39
high temperatures values of temperature and humidity is: 87 59
alarm ON
high temperatures values of temperature and humidity is : 96 49
high temperatures values of temperature and humidity is : 95/49
alarm ON
high temperatures values of temperature and humidity is : 87 52
high temperatures values of temperature and humidity is : 99 59
alarm ON
low temperature values of temperature and humidity is: 37 81
alarm OFF
high temperatures values of temperature and humidity is: 78 73
alarm ON
Low temperature values of temperature and humidity is: 40 85
high temperatures values of temperature and humidity is : 95 74
alarm ON
```

```
high temperatures values of temperature and humidity is : 59 66
alarm ON
high temperatures values of temperature and humidity is : 56 35
alarm ON
high temperatures values of temperature and humidity is: 96 79
high temperatures values of temperature and humidity is : 65 65
high temperatures values of temperature and humidity is : 94 75
high temperatures values of temperature and humidity is : 92 62
high temperatures values of temperature and humidity is : 51 57
alarm ON
high temperatures values of temperature and humidity is : 56 39
alarm ON
low temperature values of temperature and humidity is: 31 88
alarm OFF
high temperatures values of temperature and humidity is: 70 65
alarm ON
low temperature values of temperature and humidity is: 46 92
alarm OFF
high temperatures values of temperature and humidity is : 89 71
alarm ON
```