## **ASSIGNMENT-2**

Thilaga.K.S 421319106038

IOT Based Safety Gadgets for Child Safety Monitoring & Notifiction

## Program for temperature and humidity to indicate alarm continuous in high temperature using generated random variables:

```
import random
while(True):
    temp=random.randint(20,100)
    hum=random.randint(20,100)

if(temp>=60 and hum<=90):
        print("High temperature values of temperature and humidity
is:",temp,hum);
    print("Alarm ON");

elif(temp<60 and hum>90):
        print("Low temperature values of temperature and humidity
is:",temp,hum);
    print("Alarm OFF");
```

## **OUTPUT:**

```
High temperature values of temperature and humidity is: 85 49
Alarm ON
High temperature values of temperature and humidity is: 88 23
Low temperature values of temperature and humidity is: 30 97
High temperature values of temperature and humidity is: 69 50
High temperature values of temperature and humidity is: 71 90
High temperature values of temperature and humidity is: 83 32
High temperature values of temperature and humidity is: 77 42
Alarm ON
High temperature values of temperature and humidity is: 92 57
Alarm ON
High temperature values of temperature and humidity is: 95 23
High temperature values of temperature and humidity is: 66 82
High temperature values of temperature and humidity is: 86 54
High temperature values of temperature and humidity is: 96 71
High temperature values of temperature and humidity is: 86 40
High temperature values of temperature and humidity is:
```

High temperature values of temperature and	numidity is:	61 80
Alarm ON		
High temperature values of temperature and	humidity is:	99 62
Alarm ON		
High temperature values of temperature and	humidity is:	82 50
Alarm ON		
High temperature values of temperature and	humidity is:	65 85
Alarm ON		
High temperature values of temperature and	humidity is:	62 44
Alarm ON		
High temperature values of temperature and	humidity is:	98 69
Alarm ON	•	
High temperature values of temperature and	humidity is:	85 72
Alarm ON		
High temperature values of temperature and	humidity is:	87 23
Alarm ON		
High temperature values of temperature and	humidity is:	63 85
Alarm ON	numically 13.	05 05
	hound ald the class	06 33
High temperature values of temperature and	numically is:	90 33
Alarm ON		
High temperature values of temperature and	humidity is:	65 24
Alarm ON		
High temperature values of temperature and	humidity is:	84 42
Alarm ON		
High temperature values of temperature and	humidity is:	82 51
Alarm ON		
High temperature values of temperature and	humidity is:	