Assignment-4

Team ID: PNT2022TMID52016

Name: Kanjana S.K

1. Write Code and connections in wokwi for ultrasonic sensor. whatever distance is less than 100 cm send "Alert" to IBM cloud and display in device recent events.

Solution:

```
//Pins
const int TRIG_PIN = 7;
const int ECHO_PIN = 8;

//Anything over 400 cm (23200 us pulse) is "out of range"
const unsigned int MAX_DIST = 23200;

void setup() {

// The Trigger pin will tell the sensor to range find
Pin Mode(TRIG_PIN, OUTPUT);
digital Write(TRIG_PIN, LOW);

//Set Echo pin as input to measure the duration of
```

```
//pulses coming back from the distance sensor
pinMode(ECHO PIN, INPUT);
// We'll use the serial monitor to view the sensor output
 Serial.begin(9600);
}
void loop() {
unsigned long t1
unsigned long t2;
 unsigned long pulse width;
 float cm;
 float inches:
// Hold the trigger pin high for at least 10 us
digitalWrite(TRIG_PIN, HIGH);
delayMicroseconds(10);
digitalWrite(TRIG PIN, LOW);
// Wait for pulse on echo pin
while (digitalRead( ECHO PIN )==0 );
// Measure how long the echo pin was held high (pulse width)
 // Note: the micros() counter will overflow after-70 min
 t1= micros ();
 while (digitalRead(ECHO_PIN) == 1);
  t2= micros ();
  pulse_width = t2-t1;
 // Calculate distance in centimeters and inches. The constants
```

```
//are found in the datasheet, and calculated from the assumed speed
 // of sound in air at sea level (- 340m/s)
 cm=pulse Width / 58;
 inches = pulse_width/148.0;
 // Print out results
 if (pulse_width >MAX _ DIST ){
 Serial.println("Out of range");
} else {
 Serial.println("*********************************);
 Serial.print("The Measured Distance in cm: ");
Serial.println(cm);
if( cm < 100 ){
    //while(true){
    Serial.println("Alert!!");
    //}
 }
 Serial.print("*********************************);
 }
 //wait at least 1000ms before next measurement
 Delay(1000);
 }
```

Output:

1. If the distance is less than 100 cm, it alerts.

```
WOKWI TO SAVE
                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               Docs A
             hc-sr04.ino diagram.json ● Library Manager ▼
                                                                       // Pins
const int TRIG_PIN = 7;
                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      ₫00:00.466 (%58%
                                                                       const int ECHO_PIN = 8;
                                                                     // Anything over 400 cm (23200 us pulse) is "out of range" const unsigned int MAX_DIST = 23200;
                                                                       void setup() {
                                                                                   // The Trigger pin will tell the sensor to range find
pinMode(TRIG_PIN, OUTPUT);
digitalWrite(TRIG_PIN, LOW);
                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       OO UNO
                                                                                   //Set Echo pin as input to measure the duration of
//pulses coming back from the distance sensor
pinMode(ECHO_PIN, IMPUT);
                                                                                   // We'll use the serial monitor to view the sensor output Serial.begin (9600); \label{eq:serial} % \[ \frac{1}{2} \left( \frac{1}{2} \right) \left(
                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   PORT ANALOG IN
                                                                     void loop() {
                                                                                unsigned long t1;
unsigned long t2;
unsigned long pulse_width;
float cm;
float inches;
                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   The Measured Distance in cm : 84.14
                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   Alert!!
                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        W II 0
                                                                                     // Hold the trigger pin high for at least 10 us
```

2. If the distance is more than 100 cm, it won't alert

```
WOKWI B SAVE
                                                                                                                                                                               Docs
              diagram json • Library Manager •
                                                                                                  Simulation
 hc-sr04.ino
                                                                                                                                                                         Ō00:00.599 (→62%
         const int TRIG_PIN = 7;
         const int ECHO_PIN = 8;
         // Anything over 400 cm (23200 us pulse) is "out of range" const unsigned int MAX_DIST = 23200;
         void setup() {
           // The Trigger pin will tell the sensor to range find
pinMode(TRIG_PIN, OUTPUT);
                                                                                                                        SERVICE (PAR -) ES
   11
           digitalWrite(TRIG_PIN, LOW);
                                                                                                                             OO UNO
   14
15
           //Set Echo pin as input to measure the duration of
//pulses coming back from the distance sensor
pinMode(ECHO_PIN, INPUT);
   17
18
            // We'll use the serial monitor to view the sensor output
   19
           Serial.begin(9600);
   20
21
                                                                                                                            POWER ANALOG I
   22
         void loop() {
           unsigned long t1;
                                                                                               ************************
   25
           unsigned long t2;
                                                                                              The Measured Distance in cm : 227.10
            unsigned long pulse_width;
                                                                                               ********************
            float cm:
                                                                                                                                                     Activate Windows
                                                                                                                                                     Go to Settings to activate Windows
```

3. Simulation and code execution





