Team ID	PNT2022TMID39386	
Project	Hazardous Area Monitoring For Industrial	
name	Plant	

HAZARDOUS AREA MONITORING FOR INDUSTRIAL PLANT COMPONENTS LIST

Name	Quantit	Component
	y	
Arduino	1	Arduino UNO
		R3
Piezo	1	Piezo
Dc motor	1	Dc motor
Gas sensor	1	Gas sensor
Temperature	1	TMP36
sensor		
Resistor	1	1 kΩ
LED	1	Red
Bread Board	1	Bread Board
Connecting	As required	Connecting
Wires	_	Wires