ASSIGNMENT-4

Wokwi Program

Assignment Date	19 October 2022
Student Name	Sabarishkumar S
Student Roll Number	812019106301
Maximum Marks	2 Marks

Question-1

Write code and connections in wokwi for the ultrasonic sensor. Whenever the distance is less than 100 cms send an "alert" to the IBM cloud and display in thedevice recent events.


Program


```
//Pins
const int TRIG PIN = 7;
const int ECHO_PIN = 8;
//Anything over 400 cm (23200 us pulse) is "out of range"
const unsigned int MAX_DIST = 23200;
void setup(){
 // The Trigger pin will tell the sensor to range find
  pinMode(TRIG_PIN, OUTPUT);
  digitalWrite(TRIG PIN, LOW);
 //Set Echo pin as input to measure the duration of
 //pulses coming back from the distance sensor
 pinMode(ECHO_PIN, INPUT );
  // We'll use the serial monitor to view the sensor output
  Serial begin (9600);
}
void loop() {
  unsigned long t1;
  unsigned long t2;
  unsigned long pulse_width;
  float cm;
  float inches;
 // Hold the trigger pin high for at least 10 us
  digitalWrite(TRIG PIN, HIGH);
  delayMicroseconds(10);
  digitalWrite(TRIG_PIN, LOW);
  // Wait for pulse on echo pin
```

```
while (digitalRead( ECHO_PIN )==0 );
 // Measure how long the echo pin was held high (pulse width)
 // Note: the micros() counter will overflow after-70 min
 t1 = micros();
  while (digitalRead(ECHO_PIN) == 1);
 t2= micros ();
  pulse_width = t2-t1;
 // Calculate distance in centimeters and inches. The constants
 //are found in the datasheet, and calculated from the assumed speed
 // of sound in air at sea level (- 340m/s)
  cm=pulse_width/58;
  inches = pulse_width/148.0;
  // Print out results
  if (pulse_width>MAX_DIST){
    Serial println("Out of range");
   else{
      Serial_print[n("******************************);
      Serial.print("The Measured Distance in cm: ");
      Serial_println(cm);
      if( cm < 100){
        //while(true){
          Serial println("Alert!!");
    }
    Serial.print("*****************************):
//wait at least 1000ms before next measurement
delay(1000);
}
```

Output

If the distance is less than 100 cms, it alerts.





Link:

https://wokwi.com/projects/346743469024215636