```
int t=2;
int e=3;
void setup()
  Serial.begin(9600);
  pinMode(t,OUTPUT);
 pinMode(e,INPUT);
 pinMode(12,OUTPUT);
void loop()
  //ultrasonic sensor
  digitalWrite(t,LOW);
  digitalWrite(t,HIGH);
  delayMicroseconds(10);
  digitalWrite(t,LOW);
  float dur=pulseIn(e,HIGH);
  float dis=(dur*0.0343)/2;
  Serial.print("Distance is: ");
  Serial.println(dis);
    //LED ON
  if(dis >= 100)
    digitalWrite(8,HIGH);
    digitalWrite(7,HIGH);
  //Buzzer For ultrasonic Sensor
  if(dis>=100)
  for (int i=0; i <= 30000; i=i+10)
  tone(12,i);
  delay(1000);
  noTone (12);
  delay(1000);
  }
    //Temperate Sensor
  double a= analogRead(A0);
  double t=(((a/1024)*5)-0.5)*100;
  Serial.print("Temp Value: ");
  Serial.println(t);
  delay(1000);
  //LED ON
  if(t>=100)
    digitalWrite(8,HIGH);
```

```
digitalWrite(7,HIGH);
}

//Buzzer for Temperature Sensor
if(t>=100)
{
  for(int i=0; i<=30000; i=i+10)
  {
    tone(12,i);
    delay(1000);
    noTone(12);
    delay(1000);
}

//LED OFF
if(t<100)
  {
    digitalWrite(8,LOW);
    digitalWrite(7,LOW);
}
</pre>
```