

```
int sensorState = 0;
void setup()
{
 pinMode(2, INPUT);
 pinMode(13, OUTPUT);
 Serial.begin(9600);
}void loop()
 sensorState = digitalRead(2);
  if (sensorState == HIGH) {
  digitalWrite(13, HIGH);
  Serial.println("Sensor activated!");
 } else {
  digitalWrite(13, LOW);
 }
 delay(10);
}
```