ASSIGNMENT-4

B7-1A3E DINESH U

Write code and connections in wokwi for ultrasonic sensor. Whenever distance is less than 100cms, send “alert” to ibm cloud and display in device recent events.

Code;

```
#define ECHO_PIN 2
#define TRIG_PIN 3

void setup() {
  Serial.begin(115200);
  pinMode(LED_BUILTIN, OUTPUT);
  pinMode(TRIG_PIN, OUTPUT);
  pinMode(ECHO_PIN, INPUT);
}

float readDistanceCM() {
  digitalWrite(TRIG_PIN, LOW);
  delayMicroseconds(2);
  digitalWrite(TRIG_PIN, HIGH);
  delayMicroseconds(10);
  digitalWrite(TRIG_PIN, LOW);
  int duration = pulseIn(ECHO_PIN, HIGH);
  return duration * 0.034 / 2;
}

void loop() {
  float distance = readDistanceCM();

  bool isNearby = distance < 100;
```

```
  digitalWrite(LED_BUILTIN, isNearby);

  Serial.print("Measured distance: ");
  Serial.println(readDistanceCM());
  if (distance<100)
    Serial.print("alert");
  Serial.println();

  delay(100);
}
```

OUTPUT;




hc-sr04.ino - Wokwi Arduino and
wokwi.com/projects/290056311044833800
Apps
Gmail
YouTube
WhatsApp
DeviantArt - The La...
IBM
Upcoming Matches...
IBM-EPBL/IBM-Proj...
Download Microsof...
Microsoft Word 20...
Other bookmarks
WOKWI
SAVE
SHARE
hc-sr04.ino
by urish
Docs
hc-sr04.ino
diagram.json
Library Manager
#define ECHO_PIN 2
#define TRIG_PIN 3
void setup() {
Serial.begin(115200);
pinMode(LED_BUILTIN, OUTPUT);
pinMode(TRIG_PIN, OUTPUT);
pinMode(ECHO_PIN, INPUT);
}
float readDistanceCM() {
digitalWrite(TRIG_PIN, LOW);
delayMicroseconds(2);
digitalWrite(TRIG_PIN, HIGH);
delayMicroseconds(10);
digitalWrite(TRIG_PIN, LOW);
int duration = pulseIn(ECHO_PIN, HIGH);
return duration * 0.034 / 2;
}
void loop() {
float distance = readDistanceCM();
bool isNearby = distance < 100;
digitalWrite(LED_BUILTIN, isNearby);
Serial.print("Measured distance: ");
Serial.println(readDistanceCM());
if (distance<100)
Serial.print("alert");
Simulation
00:21.899
60%
UNO
ARDUINO
Measured distance: 147.36
Measured distance: 147.36
Measured distance: 147.36