Assignment -4

Question-1:

Write code and connections in wokwi for ultrasonic. Whenever distance is less than 100 cms send "alert" to ibm cloud and display in device recent events.

Solution:

```
#define ECHO_PIN 2
#define TRIG_PIN 3
#define organisation = "a09qmv"
#define deviceType = "device1"
#define deviceId ="1234"
#define authMethod ="use-token-auth"
#define authToken ="12345678"
void setup() {
Serial.begin(9600);
pinMode(TRIG_PIN, OUTPUT);
pinMode(ECHO_PIN, INPUT);
}
float readDistanceCM() {
digitalWrite(TRIG_PIN, LOW);
delayMicroseconds(2);
digitalWrite(TRIG_PIN, HIGH);
delayMicroseconds(10);
digitalWrite(TRIG_PIN, LOW);
int duration = pulseIn(ECHO_PIN, HIGH);
return duration * 0.034 / 2;
```

```
}

void loop() {

float distance = readDistanceCM();

if(distance <= 100)
{


Serial.println("person detected ");
}

else{

Serial.print("Measured distance: ");

Serial.println(readDistanceCM());
}

delay(1000); }
</pre>
```



IBM Cloud

Device Recent Events

