IOT ENABLED SMART FARMING APPLICATION

CODING:

```
#include <Servo.h>
int output1Value = 0;
int sen1Value = 0;
int sen2Value = 0;
int const gas_sensor = A1;
int const LDR = A0;
int limit = 400;
long readUltrasonicDistance(int triggerPin, int echoPin)
{
 pinMode(triggerPin, OUTPUT); // Clear the trigger
 digitalWrite(triggerPin, LOW);
 delayMicroseconds(2);
// Sets the trigger pin to HIGH state for 10 microseconds
 digitalWrite(triggerPin, HIGH);
 delayMicroseconds(10);
 digitalWrite(triggerPin, LOW);
 pinMode(echoPin, INPUT);
 // Reads the echo pin, and returns the sound wave travel time in microseconds
 return pulseIn(echoPin, HIGH);
}
```

```
Servo servo_7;
void setup()
{
 Serial.begin(9600);
                              //initialize serial communication
 pinMode(A0, INPUT);
                              //LDR
pinMode(A1,INPUT);
                              //gas sensor
pinMode(13, OUTPUT);
                                      //connected to relay
servo_7.attach(7, 500, 2500); //servo motor
 pinMode(8,OUTPUT);
                              //signal to piezo buzzer
                              //signal to PIR
 pinMode(9, INPUT);
pinMode(10, OUTPUT);
                                      //signal to npn as switch
pinMode(4, OUTPUT);
                              //Red LED
 pinMode(3, OUTPUT);
                              //Green LED
}
void loop()
{
  //----light intensity control----//
 int val1 = analogRead(LDR);
if (val1 > 500)
       {
       digitalWrite(13, LOW);
  Serial.print("Bulb ON = ");
```

```
Serial.print(val1);
      }
 else
       digitalWrite(13, HIGH);
  Serial.print("Bulb OFF = ");
 Serial.print(val1);
      }
//-----
   //---- light & fan control -----//
//-----
sen2Value = digitalRead(9);
if (sen2Value == 0)
      {
       digitalWrite(10, LOW); //npn as switch OFF
       digitalWrite(4, HIGH); // Red LED ON, indicating no motion
       digitalWrite(3, LOW); //Green LED OFF, since no Motion detected
 Serial.print(" || NO Motion Detected ");
      }
if (sen2Value == 1)
       digitalWrite(10, HIGH);//npn as switch ON
 delay(5000);
       digitalWrite(4, LOW); // RED LED OFF
       digitalWrite(3, HIGH);//GREEN LED ON, indicating motion detected
  Serial.print(" || Motion Detected!
                                   ");
      }
```

```
//-----
  // -----//
//-----
int val = analogRead(gas_sensor); //read sensor value
Serial.print("|| Gas Sensor Value = ");
Serial.print(val);
                                   //Printing in serial monitor
//val = map(val, 300, 750, 0, 100);
if (val > limit)
     {
     tone(8, 650);
     }
     delay(300);
     noTone(8);
//-----
  //-----//
//-----
sen1Value = 0.01723 * readUltrasonicDistance(6, 6);
if (sen1Value < 100)
     servo_7.write(90);
 Serial.print(" || Door Open! ; Distance = ");
 Serial.print(sen1Value);
 Serial.print("\n");
```

}

```
else

{
    servo_7.write(0);

Serial.print(" || Door Closed!; Distance = ");

Serial.print(sen1Value);

Serial.print("\n");
}

delay(10); // Delay a little bit to improve simulation performance
}
```

IMAGE:

