
ASSIGNMENT - 1 - PRATEEK RAM RA



```
CODE
int t=2;
       int e=3;
       void setup()
       {
        Serial.begin(9600);
        pinMode(t,OUTPUT);
        pinMode(e,INPUT);
        pinMode(12,OUTPUT);
       }
       void loop()
       {
        //ultrasonic sensor
        digitalWrite(t,LOW);
        digitalWrite(t,HIGH);
        delayMicroseconds(10);
        digitalWrite(t,LOW);
```

```
float dur=pulseIn(e,HIGH);
float dis=(dur*0.0343)/2;
Serial.print("Distance is: ");
Serial.println(dis);
 //LED ON
if(dis>=100)
{
 digitalWrite(8,HIGH);
 digitalWrite(7,HIGH);
}
//Buzzer For ultrasonic Sensor
if(dis>=100)
{
for(int i=0; i<=30000; i=i+10)
{
tone(12,i);
delay(1000);
noTone(12);
delay(1000);
}
}
 //Temperate Sensor
double a= analogRead(A0);
double t=(((a/1024)*5)-0.5)*100;
Serial.print("Temp Value: ");
```

```
Serial.println(t);
 delay(1000);
 //LED ON
if(t>=100)
 {
  digitalWrite(8,HIGH);
  digitalWrite(7,HIGH);
}
 //Buzzer for Temperature Sensor
 if(t>=100)
{
 for(int i=0; i<=30000; i=i+10)
{
 tone(12,i);
 delay(1000);
 noTone(12);
 delay(1000);
 }
 }
 //LED OFF
 if(t<100)
  digitalWrite(8,LOW);
  digitalWrite(7,LOW);
}
}
```