Assignment -4 WOKWI


Assignment Date	28 October 2022
Student Name	R. SIVA VASANTH
Student Roll Number	721419106030
Maximum Marks	2 Marks

Question:

Write a code and connection in wokwi for ultrasonic sensor .whenever distance is less than 100 cms send alert

Solution:

SIMULATION




CODE

```
#define ECHO_PIN 2 #define
TRIG_PIN 9 void setup() {
Serial.begin(115200);
pinMode(LED_BUILTIN, OUTPUT);
pinMode(TRIG_PIN, OUTPUT);
pinMode(ECHO_PIN, INPUT);
}
float readDistanceCM() {
digitalWrite(TRIG_PIN, LOW); delay(2);
digitalWrite(TRIG_PIN, HIGH); delay(10);
digitalWrite(TRIG_PIN, LOW); int
duration = pulseIn(ECHO_PIN, HIGH);
```


```
return duration * 0.034 / 2;
}
void loop() { float distance =
readDistanceCM(); if (distance <
100) bool is Nearby = distance < 100;
digitalWrite(LED_BUILTIN, isNearby);
Serial.println("ALERT DETECTED ");
 Serial.print("Measured distance: ");
Serial.println(readDistanceCM());
delay(100);
 }
else {
 bool isNearby = distance > 100;
digitalWrite(LED_BUILTIN, LOW);
Serial.println("ALERT NOT DETECTED");
 Serial.print("Measured distance: ");
Serial.println(readDistanceCM());
delay(100);
}
}
```

OUTPUT

When it reaches less than 100 cm, alert is detected



When the distance is greater than 100 cm, alert is not detected



PROGRAM AND OUTPUT

```
HOEFINE ECHO PIN 7
                                                                                                                                                  000:21,184 (4)86%
 2 #define TRIG PIN 4
     void setup() {
       Serial.begin(115200);
       pinWode(TRIG_PIN, OUTPUT);
       pinMode(ECHO PIN, 1901);
      fileat readDistanceCM() {
       digitalWrite(TRIG_PIN, 100);
      delay(2);
      digitalWrite(TRIG_PIN, HIGH);
      delay(10);
      digitalWrite(TRIG_PIN, []);
15 int duration = pulseIn(ECHO PIN, HIGH);
16 return duration * 0.034 / 2;
18 void loop() {
     float distance = readDistanceCM();
                                                                                Measured distance: 86.50
      # (distance < 100)[
                                                                                ALERT DETECTED
21 bool isNearby = distance < 100;
                                                                                Measured distance: 86.50
22 digitalWrite(LED_MULTIM, isWearby);
      Serial.println("ALERI DETECTED");
                                                                                ALERT DETECTED
      Serial.print("Measured distance: ");
Serial.println(readDistanceOM());
                                                                                Measured distance: 86.50
                                                                                ALERT DETECTED
       delay(180);
                                                                                Measured distance: 86.50
                                                                                                                                                       W II 1
```

REFERENCE LINK

https://wokwi.com/projects/346757092672012882