ASSIGNMENT-3

PROJECT TITLE: HAZARDOUS AREA MONITORING FOR INDUSTRIAL PLANT POWERED BY IOT TEAM LEADER: KAVIYA.V TEAM MEMBER 1: SANDHIYA DEVI.M **TEAM MEMBER 2: AJISHA.R** TEAM MEMBER3: KARTHIKA.P 1) Traffic light from gpiozero import Button, Traffi Lights, Buzzer from time import sleep buzzer = Buzzer(15) button = Button(21) lights = TrafficLights(25, 8, 7) while True: button.wait_for_press() buzzer.on() lights.green.on() sleep(1) lights.amber.on() sleep(1) lights.red.on() sleep(1) lights.off() buzzer.off() 2)blinking light import RPi.GPIO as GPIO from time import sleep GPIO.setwarnings(False)

GPIO.setmode(GPIO.BOARD)

GPIO.setup(8, GPIO.OUT, initial=GPIO.LOW)

while True:

GPIO.output(8, GPIO.HIGH)
sleep(1)
GPIO.output(8, GPIO.LOW)
sleep(1)