
Feam ID: PNT2022TMID24952

Define CS, fit into CC	1. CUSTOMER SEGMENT(S) Factories, Public buildings, Schools, Offices, Hospitals	6. CUSTOMER CONSTRAINTS Limited supervision, Lack of money for frequent servicing the equipment. No proper place for installation.	5. AVAILABLE SOLUTIONS Proper installation, good maintenance, Battery should be changed	Explore AS, different
Focus on J&P, tap into BE, understand RC	False alarm Cannot detect the fire due to aging equipment	9. PROBLEM ROOT CAUSE Steam from showers incorrect or poorly designed system. Fumes from burnt food, dust, from building work. Lack of maintenance. Incorrect installation	7. BEHAVIOUR Customer should do proper testing after specified amount of time	Focus on J&P, tap into BE, understand RC



10. YOUR SOLUTION

TR

Turn sensors away from air/vents, fans and windows. So they don't pick up any breeze drafts that could prompt the fire alarm

8. CHANNELS of BEHAVIOUR

8.1 ONLINE

Software in which emergency alarm message come should be maintained properly

8.2 OFFLINI

SL

Proper maintained should be done

|--|