SPRINT 1 TEAM ID :PNT2022TMID41407

```
#include <dht.h>
#define dht_apin A0
                                             // Analog Pin 0 is connected to DHT sensor
#define mqt_apin A1
                                             // Analog Pin 1 is connected to MQT 135
sensor dht DHT; int sensorValue;
void setup(){
 Serial.begin(9600);
                                           //Serial port to communicate with Python code
 Serial1.begin(9600);
                                            //Serial port to communicate with Wearable device
through Bluetooth (HC-05)
 delay(500);
                                        //Delay to let system boot }
void loop(){
  DHT.read11(dht_apin);
                                              // read analog input pin 0(DHT11)
sensorValue = analogRead(mqt_apin);
                                                   // read analog input pin 1(MQ135)
  //Send Humidity status to Python Code
  Serial.print("Current humidity = ");
  Serial.print(DHT.humidity);
  Serial.print("% ");
```

```
//Send Temperature status to Python Code
Serial.print("temperature = ");
Serial.print(DHT.temperature);
Serial.println("C ");
//Send AirQuality sensor value to Python code
Serial.print("AirQua=");
Serial.print(sensorValue, DEC);
Serial.println(" PPM");
//Send signals to the Wearable
Serial1.println("H T A");
Serial1.println(DHT.humidity);
Serial1.println(DHT.temperature);
Serial1.println(sensorValue, DEC);
                                       // wait 100 milliseconds for next reading }
```

delay(100);