## **ASSIGNMENT-4**

TEAM ID	PNT2022TMID52179		
NAME	N.refana		
ROLL NO	963019104006		

Write code and connection in wokwi for ultrasonic sensor. whenever distance is less than 100 cms send alert to ibm cloud and display in device recent events.

## Code:

```
# define ECHO_PIN 2
# define TRIG_PIN 3


Void setup () {
    Serial.begin(115200);
    pinMode(LED_BUILTIN, OUTPUT);
    pinMode(TRIG_PIN, OUTPUT);
    pinMode(ECHO_PIN, INPUT);
```

```
}
Float readDistanceCM() {
   digitalWrite(TRIG PIN, LOW);
   delayMicroseconds(2);
   degitalWrite(TRIG_PIN, HIGH);
   delayMicroseconds(10);
   degitalWrite(TRIG_PIN, LOW);
     int duration = pulseIn(ECHO_PIN, HIGH);
     return duration * 0.034/2;
}
void loop() {
   float distance = readDistanceCM();
   bool isNearby = distance < 100;
   digitalWrite(LED_BUILTIN, isNearby);
    Serial.print("Measured distance: ");
    Serial.print1n(readDistanceCM());
```

```
delay(100);
```

## OUTPUT:

}



Reference: <a href="https://wokwi.com/projects/290056311044833800">https://wokwi.com/projects/290056311044833800</a>